

2MASS:

For manual dithering -

```
S  
"  
W=="==E  
"  
"  
N
```

---

### [Cold Start Power Up Sequence](#)

Procedure for coming out of lightning shutdown or checking out the telescope and instrument.

---

### [2mass\\_in2\\_fill\\_instructions\\_with\\_pictures](#)

2MASS liquid Nitrogen fill instructions.

---

## Troubleshooting

- [Fourth Computer Crashes](#)

From:

<https://lavinia.as.arizona.edu/~tscopewiki/> - MOON

Permanent link:

[https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=public:catalinas:lemmon:minnesota\\_60:minnesota\\_60\\_telescope&rev=1559931469](https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=public:catalinas:lemmon:minnesota_60:minnesota_60_telescope&rev=1559931469)

Last update: **2019/06/07 11:17**

