

2MASS:

For manual dithering -

```
S
"
W=="==E
"
"
N
```

Cold Start Power Up Sequence

Procedure for coming out of lightning shutdown or checking out the telescope and instrument.

2MASS LN2 Fill Instructions With Pictures

2MASS liquid Nitrogen fill instructions.

2MASS IR Camera Checkout Form

From:

<https://lavinia.as.arizona.edu/~tscopewiki/> - **MOON**

Permanent link:

https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=public:catalinas:lemmon:minnesota_60:2mass&rev=1580850368

Last update: **2020/02/04 14:06**

