

2MASS:

For manual dithering -

```
S
"
W=="==E
"
"
N
```

[Cold Start Power Up Sequence](#)

Procedure for coming out of lightning shutdown or checking out the telescope and instrument.

[2mass_in2_fill_instructions_with_pictures](#)

2MASS liquid Nitrogen fill instructions.

[2mass_umn60_troubleshooting](#)

Common issues and how to solve them at the Minnesota 60" and 2MASS instrument.

From:
<https://lavinia.as.arizona.edu/~tscopewiki/> - MOON

Permanent link:
https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=public:catalinas:lemmon:minnesota_60:minnesota_60_telescope&rev=1559931339

Last update: 2019/06/07 11:15

