

2MASS:

For manual dithering -

```
S  
"  
W=="=="E  
"  
"  
N
```

---

### Cold Start Power Up Sequence

Procedure for coming out of lightning shutdown or checking out the telescope and instrument.

---

### [2mass\\_In2\\_fill\\_instructions\\_with\\_pictures](#)

2MASS liquid Nitrogen fill instructions.

---

# Troubleshooting

- [Fourth Computer Crashes](#)

---

From: <https://lavinia.as.arizona.edu/~tscopewiki/> - MOON

Permanent link: [https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=public:catalinas:lemmon:minnesota\\_60:minnesota\\_60\\_telescope&rev=1559931463](https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=public:catalinas:lemmon:minnesota_60:minnesota_60_telescope&rev=1559931463)

Last update: 2019/06/07 11:17

