

2MASS:

For manual dithering -

```
S
"
W=="==E
"
"
N
```

[Cold Start Power Up Sequence](#)

Procedure for coming out of lightning shutdown or checking out the telescope and instrument.

[2MASS LN2 Fill Instructions With Pictures](#)

2MASS liquid Nitrogen fill instructions.

[2MASS IR Camera Checkout Form](#)

Troubleshooting

- [Fourth Computer Crashes](#)
- [Updating Time on Big2MASS](#)

From:
<https://lavinia.as.arizona.edu/~tscopewiki/> - **MOON**

Permanent link:
https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=public:catalinas:lemmon:minnesota_60:minnesota_60_telescope&rev=1565824940

Last update: **2019/08/14 16:22**

