

What's New at the UMN60

2MASS:

For manual dithering -

```
S
"
W=="==E
"
"
N
```

Cold Start Power Up Sequence

Procedure for coming out of lightning shutdown or checking out the telescope and instrument.

2MASS LN2 Fill Instructions With Pictures

2MASS liquid Nitrogen fill instructions.

[Checkout Procedure](#) \\Procedure for checking out the 2MASS instrument.

2MASS IR Camera Checkout Form

Troubleshooting

- [Fourth Computer Crashes](#)
- [Updating Time on Big2MASS](#)
- [Jog Recovery](#)

From:
<https://lavinia.as.arizona.edu/~tscopewiki/> - MOON

Permanent link:
https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=public:catalinas:lemmon:minnesota_60:minnesota_60_telescope&rev=1576871964

Last update: 2019/12/20 12:59

