

What's New at the UMN60

2MASS:

For manual dithering -

```
S
"
W=="==E
"
"
N
```

Cold Start Power Up Sequence

Procedure for coming out of lightning shutdown or checking out the telescope and instrument.

2MASS LN2 Fill Instructions With Pictures

2MASS liquid Nitrogen fill instructions.

Checkout Procedure

Procedure for checking out the 2MASS instrument.

2MASS IR Camera Checkout Form

Troubleshooting

- [Fourth Computer Crashes](#)
- [Updating Time on Big2MASS](#)
- [Jog Recovery](#)

From:

<https://lavinia.as.arizona.edu/~tscopewiki/> - MOON

Permanent link:

https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=public:catalinas:lemmon:minnesota_60:minnesota_60_telescope&rev=1576871978

Last update: 2019/12/20 12:59

