

2MASS:

For manual dithering -

```
S
"
W=="==E
"
"
N
```

[Cold Start Power Up Sequence](#)

Procedure for coming out of lightning shutdown or checking out the telescope and instrument.

[2mass_ln2_fill_instructions_with_pictures](#)

2MASS liquid Nitrogen fill instructions.

[2mass_umn60_troubleshooting](#)

Common issues and how to solve them at the Minnesota 60" and 2MASS instrument.

From:

<https://lavinia.as.arizona.edu/~tscopewiki/> - **MOON**

Permanent link:

https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=public:lemmon:minnesota_60:minnesota_60_telescope&rev=1555979050

Last update: **2019/04/22 17:24**

