

If the Steward 90" site loses power and the generator does not start please follow the steps below:

- Do a lightning shutdown for the 90"
- Call individuals listed below starting with Larry Reddell and work your way down the list until someone is reached and the problem is reported. **Absolutely NO University of Arizona employees (which includes ALL Mountain Operations staff) are to enter the "Rock House" and try to fix the problem themselves.**

Larry Reddell  
Kitt Peak Mountain Facilities Supervisor  
318-8611

Alfredo Zazueta  
KPNO Electrician  
318-8614

Bill Wood  
90" Site Supervisor  
490-4178 cell  
790-8490 home

Joe Hoscheidt  
Mountain Operations Support Supervisor  
820-3117 cell

Paul Smith  
Mountain Operations Manager  
549-8692 cell

From:  
<https://lavinia.as.arizona.edu/~tscopewiki/> - MOON

Permanent link:  
[https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=public:kitt\\_peak:90\\_site\\_power\\_outage\\_instructions](https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=public:kitt_peak:90_site_power_outage_instructions)

Last update: 2019/06/10 11:44

