

# Shutdown

1. Using GUI move telescope to finder scope access position and replace the finder scope cover.
2. Using GUI move the Telescope to stow position
3. Close telescope cover
4. Use remote paddle to line dome shutter with eastern wall.
5. Plug in shutter motor
6. close shutter using shutter control box.
7. Shutdown TCS gui computer.
8. turn off power to telescope drives at the Telescope power box
9. switch dome control to local at the telescope power box.

From:

<https://lavinia.as.arizona.edu/~tscopewiki/> - **MOON**

Permanent link:

[https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=21\\_inch:lightning\\_shutdown&rev=1365535242](https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=21_inch:lightning_shutdown&rev=1365535242)

Last update: **2013/04/09 12:20**

