

VATT Spectrograph

Documentation

-Cold Start (from lightning shutdown)

Maintenance

-Argon Calibration Lamp was replaced on 4/26/2013.

Note: There is some concern the lamps are burning out faster than they should.

From:

<https://lavinia.as.arizona.edu/~tscopewiki/> - **MOON**

Permanent link:

<https://lavinia.as.arizona.edu/~tscopewiki/doku.php?id=vatt:vattspec&rev=1377885813>

Last update: **2013/08/30 11:03**

